


Makertech

Stage 08: Wiring

Wiring guide for the Axis 3d printer.

Written By: Makertech






TOOLS:



- [Scissors](#) (1)
- [Lighter](#) (1)
- [Measuring Tape](#) (1)
- [Small flat/cross head screw driver](#) (1)

Step 1 — Extruder Cable Sleeving





- ① Cut 70CM of the braided cable sleeving.
- Use a lighter to melt the ends to prevent fraying.

Step 2 — Extruder Cables




- Take two 1m motor cables.
 - Thread the sleaving over both of them.
 - Plug one of the cables into the extruder motor.
 - Cable tie that cable to the spool holder bracket.
- ☞ Note, the second cable is there for the dual extrusion upgrade, it is installed now even if you don't have that upgrade.

Step 3 — Cable Tying to Gantry




- Turn the lead screw to bring the gantry all of the way down, the hotend should be touching the print surface.
- Cable tie both bunches of cables together to the gantry.

Step 4 — Y-Axis Cable Slewing





- ① Cut 45CM of the braided cable sleeving.
- Use a lighter to melt the ends to prevent fraying.

Step 5 — Y-Axis Cables



- Raise the gantry to the very top.
- Plug a 1M motor cable into the y-motor.
- Slide the 45CM cable sleeving over the motor cable and Y-endstop.
- Cable tie to the bottom of the gantry.



Step 6 — Tying All Cables



☒ Before tying off the cables together, it may be worth using tape to mark what each of the cables is connected to.


- Place the Axis on its side like shown. Use multiple cable ties to create a single branch of cable.
- Push all of the cables through the square hole in the back of the base.
- Use a cable tie to attach the cable branch to the base.

Step 7 — Y-Axis Wiring




- Plug the Y-axis (gantry) motor into the control board.
- Plug the Y-endstop into the control board.

Step 8 — Extruder Motor





- Plug the extruder motor cable into the control board like shown.

Step 9 — Part Cooling Fan




- Plug the part cooling fan cable into the control board like shown.

Step 10 — Hotend




- Plug the hotend thermistor into the control board.
- Secure the hotend heater cables to the terminals on the control board.
- ☑ Their polarity does not matter.

Step 11 — Hotend Fan and Probe





- i** First prepare the 30mm hotend fan (the smaller fan that connects directly onto the hotend) by cutting of the connector and exposing some of the wire.
- Unplug the power cables from the control board.
 - Take the red power cable, the red 30mm hotend fan cable and the brown cable from the probe and wind together.
 - Plug all three back into the control board and secure the terminal tightly.

Step 12 — Hotend Fan and Probe cont.



- Take the remaining black power cable and black cable from the hotend fan and wind together.
- Plug both back into the control board and secure the terminal tightly.




Step 13 — Probe Cables



- Plug the black and blue probe cables into the positions shown on the control board.
- Black to D32
- Blue to GND

⚠ NOTE: There is an empty pin between the black and blue cables!


Step 14 — X-Motor Cable



- ① Take one of the 50CM motor cables.
- Plug one end into the X-motor.
- Plug the other end into the control board.


This document was generated on 2021-12-26 11:53:29 AM (MST).

Step 15 — Z-Motor Cable




- ① Take the remaining 50CM motor cable.
- Plug one end into the Z-motor.
- Plug the other end into the control board.

Step 16 — Tidying the Cables



- Use cable ties to bunch the cables up like shown.

Step 17 — TMC2208 Drivers



✦ Skip this step if you do not have the TMC2208 driver upgrade.



⚠ The stepper drivers are the most delicate part of the Axis 3d printer and it is why we've also included a spare. Before opening, make sure that you are grounded (touch a large metal object) to avoid any chance of static damage.

i The TMC2208 upgrade comes with either 3 or 6 drivers. If you have three you can use two on the x/y axes and keep one as spare, if you have 6 you can use them on the X/Y/Z/E0 (and E1 for dual extrusion) and have one spare.

- Prepare the TMC2208 stepper drivers by removing them from their packaging and sticking the heat-sink to the top.

✦ Make sure that the heat-sink is not touching any of the pins. Orient the fins of the heat-sink as shown.

Step 18 — Installing the TMC2208 Drivers




☞ Skip this step if you do not have the TMC2208 driver upgrade.

- To install the TMC2208 drivers you will need to make sure that there are no jumpers plugged in at the stepper driver locations on the control board.
- You will however need to make sure that there is one jumper placed on the UART pins for each axis you have a TMC2208 installed.
- Plug the TMC2208 driver into the positions shown, make sure that the trim-pot is pointing towards the power terminals, installing the driver the wrong way round will destroy it.

☞ Note, the trim-pot doesn't need adjusting as these drivers allow us to control the current via the firmware.




Step 19 — Preparing the Stepper Drivers



⚠ The stepper drivers are the most delicate part of the Axis 3d printer and it is why we've also included a spare. Before opening, make sure that you are grounded (touch a large metal object) to avoid any chance of static damage.

- Prepare the A4988 stepper drivers by removing them from their packaging and sticking the heat-sink to the black chip.
- ☒ Make sure that the heat-sink is not touching any of the pins. Orient the fins of the heat-sink as shown.
- **Trimpot:** Adjust the trimpot so that flat side is pointing left as shown in the second photo.

Step 20 — Installing the A4988 Stepper Drivers



- If you do not have any of the TMC2208 drivers you will need to install the A4988 drivers like shown.
- Under the A4988 driver positions on the control board there needs to be three jumpers installed like shown in the second and third photo.
- Make sure that all of the drivers are orientated with their trim-pots pointing away from power terminals.

⚠ Plugging them in the wrong way round will destroy them.